

DATE: April 5, 2010

PRODUCT: ALL 2010/11 BLUE BIRD ALL AMERICAN D3 MODELS

COMPONENT: HORN CONTACT

ISSUE: Premature wear of the horn contact (fig.1) located in the steering column (fig.2 #15) may cause the horn to not sound when the horn button is pressed. Blue Bird is aware of the issue and is working on a solution.

REPAIR: If the horn is not working properly inspect the condition of the horn contact (fig.1), if failed, contact your parts representative to order a replacement horn contact part number 10006555, remove the failed contact and install the new contact.

